



AC SPEED CONTROLLER & 3 PHASE MOTOR WIRING DIAGRAM



3 PHASE LEESON MOTOR



Pitching Motor Wiring Diagram			
Power Cord	Motor Wires	Motor Wires	Motor Wires
Black Wire	1	7	
White Wire	2	8	
Green Wire	Ground Screw		
Red Wire	3	9	
Wire Nut	6	5	4