



## AC SPEED CONTROLLER & 3 PHASE MOTOR WIRING DIAGRAM



## 3 PHASE US MOTOR MODEL #F016 WIRING DIAGRAM



Pitching Motor Wiring Diagram			
Power Cord	Motor Wires	Motor Wires	Motor Wires
Black Wire	3	9	
White Wire	2	8	
Green Wire	Ground Screw		
Red Wire	1	7	
Wire Nut	6	5	4