



SERVICING YOUR EQUIPMENT



Note:
With the jumper installed as shown Cage 1 must be on for the Computer to have power.

Remove this cord to program at lightbox, replace original cord when done.



* Unfiltered DC	
Multimeter Setting	Reading
DC Volts	12
AC Volts	6.5

DWG 90740012