


Cage 1	
All Other Cages	

**Note:**  
With the jumper installed as shown Cage 1 must be on for the Computer to have power.

Common  
SIO 1 (Coin, Speed, Elevation)(12 Vdc\*)  
Common  
SIO 1 (Coin, Speed, Elevation)(12 Vdc\*)  
Common  
SIO 2 (Computer)(12 Vdc\*)  
Common  
SIO 2 (Computer)(12 Vdc\*)  
Common



White Neutral  
Feed B White Neutral  
Feed A White Neutral  
Pitch B White Neutral  
Pitch A White Neutral  
White Neutral  
Black Hot

AC IN

* Unfiltered DC		
Multimeter Setting		Reading
DC Volts		12
AC Volts		6.5

DWG 90740012